



TECTIUM™ FILLER AND GLAZE DAMAGED METAL PART



DRIVING SURFACE PERFECTION™



Step 1: Inspect panel

- Clean and inspect panel.
- Use appropriate Axalta silicone remover and a suitable degreasing cloth to clean the surface. For more details refer to "Preparatory surface degreasing SOP".

Step 2: Prepare substrate

- Sand with DA/orbital sander and P80-abrasive discs to remove existing paintwork in readiness for U-POL Tectium Filler application.

Step 3: Apply U-POL UP0643 Tectium™ Filler

- Blow off panel and clean thoroughly by using an appropriate Axalta silicone remover.
- Mix Tectium Filler @ 2% activation ratio, apply and allow filler to dry 15 – 20 minutes @ 70F/21C according to the Tectium Filler technical data sheet.
- Sand Tectium Filler to shape using a hand block and P80-P120 followed by P180-P240 abrasive strips.
- Use **UPOL UP0873 GUIDE #7** guide coat during all sanding steps of the repair.
- Blow off panel and repeat step 3 if required. Removing dust from pores and voids is of particular importance prior to the application of another layer of Tectium Filler.

Step 4: Apply U-POL UP0645 Tectium™ Glaze

- Blow off panel. Use appropriate (Axalta) silicone remover and a suitable degreasing cloth to clean the surface.
- Mix Tectium Glaze @ 2% activation ratio, apply and allow glaze to dry 10-15 minutes @ 70F/21C according to the Tectium Glaze technical data sheet.
- Sand Tectium Glaze using a hand block and P180, final sand with P180-P240 abrasive strips.
- Use **UPOL UP0873 GUIDE #7** guide coat during all sanding steps of the repair.

Step 5: Apply U-POL UP0686 MicroFill (Optional)

- Blow off panel. Removal of dust from micro-pores and voids is of particular importance prior to the application of MicroFill.
- Use appropriate (Axalta) silicone remover and a suitable degreasing cloth to clean the surface.
- Fill small voids or micro pores / pin-holes prior to the application of primer, surfacer or sealer by wiping MicroFill over the filler / glaze surface using a lint free cloth. Remove excess with a clean cloth.

Step 6: Apply surfacer/filler

- If applying MicroFill, allow to dry for 15 mins (@ 70F/21C) before applying Axalta solvent-based primer / surfacer or sealer. Refer to MicroFill TDS Guide for additional technical information.

Step 7: Prepare for top coating

- Apply U-POL GUIDE #7 guide coat and sand primed repair area with a hand block and P320-P400 abrasive strip if necessary.
- Re-apply GUIDE #7 guide coat, sand edges and corners with a suitable foam backed abrasive followed by DA/orbital machine sanding with P500-P600 abrasive discs.
- Clean thoroughly using an appropriate Axalta silicone remover or water-based cleaner depending on local VOC legislation in readiness for your chosen clear over base system to be applied.
- Apply appropriate Axalta topcoat system.



BE SMART:
CLEAN AND TIDY UP



axalta.com

Disclaimer: Check with local regulations to ensure the relevant safety regulations and recommendations meet with local, state, province, region and/or country safety and environmental compliance standards. All information, illustrations and specifications on this process poster are based on the latest product information available at the time of release. Not all products or product systems on this poster may be available in your country and/or region, please contact your local Axalta organization for additional information. Axalta reserves the right to make changes at any time without notice.